

SPECIFICATION:

page 5, line 14:

The upper oblong members {[16, 16']} 14, 14' have predrilled predrilled top fasteners holes 36, 36' through which mechanical fasteners pass in order to connect with wooden braces (not shown) themselves being part of the tabletop 28.